

## Basic Details

### Publish Date

16 February 2026

### Case ID#

3347

### Title

Assessment of unexplained reservoir water loss: Incident response and ongoing integrity investigation (not high-risk reservoir)

### Nation

Wales

### Regulator Reference No.

75

### Legal Status

Statutory

### Reservoir Type

Impounding

### Reservoir Capacity

10 - 24,999m3

### Year of Construction

1950 - 1969

### Main Construction Type

Earth fill embankment

### Dam Height

15 - 29.99 metres

### Dam Flood Category

D

### Hazard Class

Not-high-risk reservoir

### Reservoir Use

- Industrial process

### Owner Type

Limited company

# Incident Details

## Date & Time of Incident

27 September 2024 - 12:00

## Date Incident Closed

04 November 2025

## Observations that Caused the Incident to be Declared

- Leakage or seepage from a new leakage point

## Describe the Incident

It was observed that the reservoir was not maintaining its normal operating water level. No specific trigger was identified. Historical incidents in 2019 and 2022 showed similar symptoms (unexplained water loss). Following a more recent investigation, a possible defect in the upstream embankment was observed following a spring tide. The defect became submerged following heavy rain. A boom has been installed upstream of the defect until temporary and/or permanent repairs can be carried out.

## Supporting Photos

□

# Causes and Impacts

## Natural Processes which Initiated or Contributed to the Incident

- Unknown

## Main Contributing Factors to the Incident Occurring

### Dam Factors

- Other dam factors (describe below)
- Unknown

### External Factors

- None

## Shortcomings

- Unknown

## Root Cause of the Incident

Unknown - investigations ongoing

## Impacts on the Reservoir

- Other (describe below)

## Supporting Photos

No images provided.

## Supporting Contributions and Studies

### Human Factors which Influenced the Incident

No human factors identified. No issues with protocols, training, or record keeping were reported.

### Instrumentation at the Reservoir

No instrumentation was installed or used. Monitoring relied on visual inspections and drone surveys.

### Was Instrumentation Effective?

Not Applicable

### Assistance by External Parties and Impacts on Downstream Population

Regulator notified. No evacuations or downstream impacts.

### Summary of Studies or Investigations Undertaken

Drone survey (inconclusive). Dye testing of underdrainage catch boxes. Visual inspection during low water levels. Planned further investigation and repair in mid-2026.

### Supporting Photos

No images provided.

## Lessons Learnt

### Lesson 1

To be confirmed after further investigation. Historical incidents suggest need for improved liner integrity and monitoring.

### Lesson 2

### Lesson 3

### Lesson 4

### Closing Comments

Further investigations are planned to confirm root cause, remedial measures and to set out lessons learnt.

### Supporting Photos

No images provided.

Information provided has been sent from reservoir owners and engineers, and cleansed of personal information by the enforcement authority. We cannot guarantee the accuracy of the data, but if you find an error please contact the relevant enforcement authority.